



Subject: Electric starter

Affected engine models: All engine models:

L 2000 EA

Background Information: The previously used starter BOSCH 0,4 kW is no longer available.

Priority: without

Compliance: Engines in production may be equipped with the starters BOSCH 1,4 kW or SJCE 0,9 kW immediately. In both cases the starter mounts must be replaced. In addition the starter ring gear must be replaced when using the BOSCH 1,4 kW starter.
Engines in service may be optionally equipped with the new starters. Consult the airframe manufacturer for changes to the propeller pitch adjustment (if necessary).

This document has been translated to the best of our knowledge. In case of doubt however only the german original shall be considered authoritative.

LBA approved:



[Handwritten signature]

0 2. MAI 1994

Bearb.: Stolinski



Replaces Edition from: 25.02.93

Page: 1

Gepr.: *B. Ederly*

Edition: 06.04.94

of 1 Pages