

Subject: Sealing compound ELASTOSIL N189, Part Number: 708.413.004.000
Sealing compound CURIL-C, Part Number: 170.211.210.000

Affected engine models: All engine models:

L 1700
L 2000
L 2400

Background information: The above-mentioned sealing compounds are no longer used.

Priority: On occurrence of leaks, repairs, overhaul and manufacture of affected parts.

Compliance: The above sealants are replaced as follows:

Sealing compound	replaced by
ELASTOSIL N189, Part Number: 708.413.004.000	Sealing compound 708.413.070.000
CURIL-C, Part Number: 170.211.210.000	Sealing compound 708.413.075.000 Not for valve cover gasket!
For valve cover gasket	Sealing compound 708.413.080.000

Note: During assembly, the relevant parts must be dry before the sealant is applied, be free of grease, dust and dirt. To ensure good adhesion of 708.413.075.000 to shaft seals, their contact surfaces must be pretreated with primer 708.413.065.000.

This document has been translated to the best of our knowledge. In case of doubt however only the German original shall be considered authoritative.

Source: Limbach Flugmotoren GmbH, Kotthausener Str.5, 53639 Königswinter, Germany
Tel: 02244-92010, Fax: 02244-920130, www.limflug.de

Approval: The technical content of this document is approved under the Authority of EASA ref. approval number 10080637 and have been produced in accordance with alternative procedure to DOA nr. EASA.AP509.