

Subject: Electronic Control Unit (ECU)

Affected engine models: All engine models:

L 2400 EF, DF, ET, DT

Background information: Production of current ECU, type PI 038, P/N: 250.127.400.000 terminated.

Priority: none

Compliance: The ECU type PI 038, P/N: 250.127.400.000 is replaced by ECU type PI 048, P/N: 250.127.405.000 with immediate effect.

Caution: When using the ECU type PI 048, P/N: 250.127.405.000, the connector T1 must be connected with the coil T2 and connector T2 must be connected with coil T1. For engines with dual ignition that applies to both ignition circuits.

Note: This document has been translated to the best of our knowledge. In case of doubt however only the German original shall be considered authoritative.

Approval: This Technical Bulletin is approved in accordance with the procedures of the LBA approved development organisation LBA.NSD.006.

905.700.062.005

Bearb.: Stolinski

Replaces Edition from:

Page: 1 of 1 Pages

Gepr. + Freig.:

Edition: 13.02.02

Reg.-Nr.: 036 Datei: TB62.doc